



# MONTANA FISH, WILDLIFE & PARKS

## ADDENDUM NO. 1

---

TO: ALL BIDDERS OF RECORD

PROJECT: Travelers' Rest State Park – Visitor Center Re-roof

FWP PROJECT #: 7196110

DATE: 11/12/19

FROM: Jon Maxwell, P.E., Montana FWP Project Manager

**Acknowledge receipt of this addendum by inserting its number and date in the Proposal Form and on the Bid Envelope. Failure to do so may subject bidder to disqualification.**

This Addendum forms a part of the Contract Documents. Clarification and/or modifications area as follows:

1) *Can standing seam be substituted for this project?*

Due to the open purlin construction and associated spans, standing seam is not recommended for this project. 26 gauge 'Delta Rib' style is specified, and due to the open purlin spans, a Purlin Bearing Rib (PBR) panel typically rated for spans up to 5 feet will be required.

2) *Can photos of the roof structure be provided?*

Interior and exterior photos taken by the insurance adjuster are provided as part of this addendum. Roof structure photos show the trussed sections of the building. Due to ceiling finishes attached directly to the underside of the rafters, those sections are inaccessible without removing roof panels. Photos taken of rafter sections where panels were removed for inspection are shown on Sheet 4 of the Drawings.

3) *What is the expected timeframe for the project?*

If an acceptable bid is received, a Notice of Award will be issued the week of November 26, and typically takes 2-3 weeks to finalize a contract. A Notice-to-Proceed will then be issued after materials are procured and when weather conditions are appropriate to complete the project. Winter conditions may necessitate a delay until spring, but is not expected to extend beyond May 1, 2020.

**END OF ADDENDUM NO. 1**

## Montana Claims Service of Missoula

---

P.O. Box 4504  
Missoula, MT 59806  
Phone (406) 542-2580  
Fax (406) 543-2822  
Email MCSM@Montana.com

Insured: Department of FWP / Travelers Rest State Park  
Property: 6717 U.S. Hwy 12  
Lolo, MT 59847

Claim Rep.: Gordon Amsbaugh  
Company: Risk Management - State of Montana

Estimator: Bill Whalen  
Company: Montana Claims Service of Missoula

**Claim Number:** P28611-FW

**Policy Number:** N/A

**Type of Loss:** Weight of Ice & Snow

Date Contacted: 7/2/2019

Date of Loss: 1/1/2019

Date Inspected: 7/12/2019

Date Received: 6/28/2019

Date Entered: 7/15/2019 10:24 PM

Price List: MTMI8X\_JUL19  
Restoration/Service/Remodel  
Estimate: 100019-FWP\_EXT\_PICS

**EXTERIOR PHOTO SHEETS - OVERALL VIEWS AND ROOF DAMAGES**

## Montana Claims Service of Missoula

---

P.O. Box 4504  
Missoula, MT 59806  
Phone (406) 542-2580  
Fax (406) 543-2822  
Email MCSM@Montana.com

1 1-DSCN3842

Date Taken: 7/12/2019

Taken By: Bill Whalen

Front view of insured Museum  
Building



2 2-DSCN3843

Date Taken: 7/12/2019

Taken By: Bill Whalen

View of North facing roof slope of  
insured Museum Building





## Montana Claims Service of Missoula

---

P.O. Box 4504  
Missoula, MT 59806  
Phone (406) 542-2580  
Fax (406) 543-2822  
Email MCSM@Montana.com

3 3-DSCN3844

Date Taken: 7/12/2019

Taken By: Bill Whalen

Ground view to W across main N  
facing roof slope.



4 4-DSCN3846

Date Taken: 7/12/2019

Taken By: Bill Whalen

Ground view to W across main N  
facing roof slope.



## Montana Claims Service of Missoula

---

P.O. Box 4504  
Missoula, MT 59806  
Phone (406) 542-2580  
Fax (406) 543-2822  
Email MCSM@Montana.com

5 5-DSCN3845

Date Taken: 7/12/2019

Taken By: Bill Whalen

View from ground of North facing  
roof slope of insured Museum  
Building with raised overlap joints  
marked.



6 6-DSCN3804

Date Taken: 7/12/2019

Taken By: Bill Whalen

View to W across main N facing roof  
slope.



## Montana Claims Service of Missoula

---

P.O. Box 4504  
Missoula, MT 59806  
Phone (406) 542-2580  
Fax (406) 543-2822  
Email MCSM@Montana.com

7 7-DSCN3805

Date Taken: 7/12/2019

Taken By: Bill Whalen

View down main N facing roof slope  
with belly from snow load marked.



8 8-DSCN3806

Date Taken: 7/12/2019

Taken By: Bill Whalen

View down main N facing roof slope  
with belly from snow load marked.





## Montana Claims Service of Missoula

---

P.O. Box 4504  
Missoula, MT 59806  
Phone (406) 542-2580  
Fax (406) 543-2822  
Email MCSM@Montana.com

9 9-DSCN3807

Date Taken: 7/12/2019

Taken By: Bill Whalen

View down main N facing roof slope  
with belly from snow load marked.



10 10-DSCN3808

Date Taken: 7/12/2019

Taken By: Bill Whalen

View down main N facing roof slope  
with belly from snow load marked.



## Montana Claims Service of Missoula

---

P.O. Box 4504  
Missoula, MT 59806  
Phone (406) 542-2580  
Fax (406) 543-2822  
Email MCSM@Montana.com

11 11-DSCN3809

Date Taken: 7/12/2019

Taken By: Bill Whalen

View of separated lateral seam along  
joints of roof metal.




12 12-DSCN3810

Date Taken: 7/12/2019

Taken By: Bill Whalen

View of separated lateral seam along  
joints of roof metal.





## Montana Claims Service of Missoula

---

P.O. Box 4504  
Missoula, MT 59806  
Phone (406) 542-2580  
Fax (406) 543-2822  
Email MCSM@Montana.com

13 13-DSCN3827

Date Taken: 7/12/2019

Taken By: Bill Whalen

View to W across N facing roof slope.  
Area of prior, partial replacement is  
marked.



14 14-DSCN3828

Date Taken: 7/12/2019

Taken By: Bill Whalen

View to W across N facing roof slope.  
Area of prior, partial replacement is  
marked.



## Montana Claims Service of Missoula

---

P.O. Box 4504  
Missoula, MT 59806  
Phone (406) 542-2580  
Fax (406) 543-2822  
Email MCSM@Montana.com

15 15-DSCN3829

Date Taken: 7/12/2019

Taken By: Bill Whalen

N facing roof slope - Separation of  
overlap joint from weight of ice and  
snow.



16 16-DSCN3830

Date Taken: 7/12/2019

Taken By: Bill Whalen

N facing roof slope - Separation of  
overlap joint from weight of ice and  
snow.



## Montana Claims Service of Missoula

---

P.O. Box 4504  
Missoula, MT 59806  
Phone (406) 542-2580  
Fax (406) 543-2822  
Email MCSM@Montana.com

17 17-DSCN3831

Date Taken: 7/12/2019

Taken By: Bill Whalen

N facing roof slope - Separation of  
overlap joint from weight of ice and  
snow.




18 18-DSCN3833

Date Taken: 7/12/2019

Taken By: Bill Whalen

View to E across main N facing roof  
slope with separations at roof metal  
joints visible.





## Montana Claims Service of Missoula

---

P.O. Box 4504  
Missoula, MT 59806  
Phone (406) 542-2580  
Fax (406) 543-2822  
Email MCSM@Montana.com

19 19-DSCN3834

Date Taken: 7/12/2019

Taken By: Bill Whalen

N facing roof slope - Separation of  
overlap joint from weight of ice and  
snow.



20 20-DSCN3841

Date Taken: 7/12/2019

Taken By: Bill Whalen

View of South facing roof slope of  
insured Museum Building and Gift  
Shop.



## Montana Claims Service of Missoula

---

P.O. Box 4504  
Missoula, MT 59806  
Phone (406) 542-2580  
Fax (406) 543-2822  
Email MCSM@Montana.com

- 21 21-DSCN3795  
Date Taken: 7/12/2019  
Taken By: Bill Whalen  
Entry Porch Roof - No damage.



- 22 22-DSCN3787  
Date Taken: 7/12/2019  
Taken By: Bill Whalen  
Overall view of Gift Shop roof.





## Montana Claims Service of Missoula

---

P.O. Box 4504  
Missoula, MT 59806  
Phone (406) 542-2580  
Fax (406) 543-2822  
Email MCSM@Montana.com

23 23-DSCN3788

Date Taken: 7/12/2019

Taken By: Bill Whalen

Upper edge flashing of Gift Shop  
Roof.



24 24-DSCN3789

Date Taken: 7/12/2019

Taken By: Bill Whalen

Overall view down Gift Shop Roof  
with damaged areas marked.





## Montana Claims Service of Missoula

---


P.O. Box 4504  
Missoula, MT 59806  
Phone (406) 542-2580  
Fax (406) 543-2822  
Email MCSM@Montana.com

25 25-DSCN3792

Date Taken: 7/12/2019

Taken By: Bill Whalen

Overall view down Gift Shop Roof  
slope with damaged areas marked




26 26-DSCN3791

Date Taken: 7/12/2019

Taken By: Bill Whalen

Overall view down Gift Shop Roof  
slope with damaged areas marked



## Montana Claims Service of Missoula

---

P.O. Box 4504  
Missoula, MT 59806  
Phone (406) 542-2580  
Fax (406) 543-2822  
Email MCSM@Montana.com

27 27-DSCN3793

Date Taken: 7/12/2019

Taken By: Bill Whalen

View across Gift Shop roof with rows  
of screws pulled/displaced.



28 28-DSCN3796

Date Taken: 7/12/2019

Taken By: Bill Whalen

View along drip edge of Gift Shop  
roof with rows of screws  
pulled/displaced by ice and snow.



## Montana Claims Service of Missoula

---

P.O. Box 4504  
Missoula, MT 59806  
Phone (406) 542-2580  
Fax (406) 543-2822  
Email MCSM@Montana.com

29 29-DSCN3797

Date Taken: 7/12/2019

Taken By: Bill Whalen

View along drip edge of Gift Shop  
roof with rows of screws  
pulled/displaced by ice and snow.



30 30-DSCN3798

Date Taken: 7/12/2019

Taken By: Bill Whalen

View along drip edge of Gift Shop  
roof with rows of screws  
pulled/displaced by ice and snow.





## Montana Claims Service of Missoula

---

P.O. Box 4504  
Missoula, MT 59806  
Phone (406) 542-2580  
Fax (406) 543-2822  
Email MCSM@Montana.com

31 31-DSCN3800

Date Taken: 7/12/2019

Taken By: Bill Whalen

View along drip edge of Gift Shop roof with rows of screws pulled/displaced by ice and snow.



32 32-DSCN3801

Date Taken: 7/12/2019

Taken By: Bill Whalen

View along drip edge and inner flashing of Gift Shop roof with damage from ice and snow.



## Montana Claims Service of Missoula

---

P.O. Box 4504  
Missoula, MT 59806  
Phone (406) 542-2580  
Fax (406) 543-2822  
Email MCSM@Montana.com

33 33-DSCN3848

Date Taken: 7/12/2019

Taken By: Bill Whalen

View of South facing roof slope of  
insured Museum Building



34 34-DSCN3849

Date Taken: 7/12/2019

Taken By: Bill Whalen

View from ground of South facing  
roof slope of insured Museum  
Building with raised overlap joints  
marked.



## Montana Claims Service of Missoula

---

P.O. Box 4504  
Missoula, MT 59806  
Phone (406) 542-2580  
Fax (406) 543-2822  
Email MCSM@Montana.com

35 35-DSCN3851

Date Taken: 7/12/2019

Taken By: Bill Whalen

View from ground of South facing  
roof slope of insured Museum  
Building with raised overlap joints  
marked.



36 36-DSCN3853

Date Taken: 7/12/2019

Taken By: Bill Whalen

View from ground of South facing  
roof slope of insured Museum  
Building with raised overlap joints  
marked.





## Montana Claims Service of Missoula

---


P.O. Box 4504  
Missoula, MT 59806  
Phone (406) 542-2580  
Fax (406) 543-2822  
Email MCSM@Montana.com

37 37-DSCN3852

Date Taken: 7/12/2019

Taken By: Bill Whalen

View from ground of South facing  
roof slope of insured Museum  
Building with raised overlap joints  
marked.



38 38-DSCN3803

Date Taken: 7/12/2019

Taken By: Bill Whalen

View of flashing along step-up  
between Gift Shop and main South  
facing roof slope.



## Montana Claims Service of Missoula

---

P.O. Box 4504  
Missoula, MT 59806  
Phone (406) 542-2580  
Fax (406) 543-2822  
Email MCSM@Montana.com

39 39-DSCN3802

Date Taken: 7/12/2019

Taken By: Bill Whalen

View to West along South facing roof slope of insured Museum Building.



40 40-DSCN3812

Date Taken: 7/12/2019

Taken By: Bill Whalen

View down S facing roof slope at East end. Belly area from snow load is marked.



## Montana Claims Service of Missoula

---

P.O. Box 4504  
Missoula, MT 59806  
Phone (406) 542-2580  
Fax (406) 543-2822  
Email MCSM@Montana.com

41 41-DSCN3813

Date Taken: 7/12/2019

Taken By: Bill Whalen

View down S facing roof slope at East end. Belly area from snow load is marked.



42 42-DSCN3815

Date Taken: 7/12/2019

Taken By: Bill Whalen

Damaged rows of screws on South facing roof slope.





## Montana Claims Service of Missoula


P.O. Box 4504  
Missoula, MT 59806  
Phone (406) 542-2580  
Fax (406) 543-2822  
Email MCSM@Montana.com

43 43-DSCN3816

Date Taken: 7/12/2019

Taken By: Bill Whalen

Damaged rows of screws on South facing roof slope.



44 44-DSCN3818

Date Taken: 7/12/2019

Taken By: Bill Whalen

View to W across W end of S facing roof slope. Area of prior, partial replacement is marked.



## Montana Claims Service of Missoula

---


P.O. Box 4504  
Missoula, MT 59806  
Phone (406) 542-2580  
Fax (406) 543-2822  
Email MCSM@Montana.com

45 45-DSCN3819

Date Taken: 7/12/2019

Taken By: Bill Whalen

S facing roof slope - Separation of  
overlap joint from weight of ice and  
snow.




46 46-DSCN3820

Date Taken: 7/12/2019

Taken By: Bill Whalen

S facing roof slope - Separation of  
overlap joint from weight of ice and  
snow.



## Montana Claims Service of Missoula

---

P.O. Box 4504  
Missoula, MT 59806  
Phone (406) 542-2580  
Fax (406) 543-2822  
Email MCSM@Montana.com

47 47-DSCN3822

Date Taken: 7/12/2019

Taken By: Bill Whalen

S facing roof slope - Separation of  
overlap joint from weight of ice and  
snow.



48 48-DSCN3823

Date Taken: 7/12/2019

Taken By: Bill Whalen

S facing roof slope - Separation of  
overlap joint from weight of ice and  
snow.





## Montana Claims Service of Missoula

---

P.O. Box 4504  
Missoula, MT 59806  
Phone (406) 542-2580  
Fax (406) 543-2822  
Email MCSM@Montana.com

49 49-DSCN3824

Date Taken: 7/12/2019

Taken By: Bill Whalen

S facing roof slope - Separation of  
overlap joint from weight of ice and  
snow.



50 50-DSCN3825

Date Taken: 7/12/2019

Taken By: Bill Whalen

S facing roof slope - Separation of  
overlap joint from weight of ice and  
snow.



## Montana Claims Service of Missoula

---

P.O. Box 4504  
Missoula, MT 59806  
Phone (406) 542-2580  
Fax (406) 543-2822  
Email MCSM@Montana.com

51 51-DSCN3826

Date Taken: 7/12/2019

Taken By: Bill Whalen

S facing roof slope - Separation of  
overlap joint from weight of ice and  
snow.



52 52-DSCN3769

Date Taken: 7/12/2019

Taken By: Bill Whalen

View to E across attic area and trusses  
/ No visible damage from roof leakage  
noted.



## Montana Claims Service of Missoula

---

P.O. Box 4504  
Missoula, MT 59806  
Phone (406) 542-2580  
Fax (406) 543-2822  
Email MCSM@Montana.com

53 53-DSCN3771

Date Taken: 7/12/2019

Taken By: Bill Whalen

View to S across attic area and trusses  
/ No visible damage from roof leakage  
noted.



54 54-DSCN3775

Date Taken: 7/12/2019

Taken By: Bill Whalen

View to S across attic area and trusses  
/ No visible damage from roof leakage  
noted.





## Montana Claims Service of Missoula

---

P.O. Box 4504  
Missoula, MT 59806  
Phone (406) 542-2580  
Fax (406) 543-2822  
Email MCSM@Montana.com

55 55-DSCN3772

Date Taken: 7/12/2019

Taken By: Bill Whalen

View to W across attic area and  
trusses / No visible damage from roof  
leakage noted.



56 56-DSCN3776

Date Taken: 7/12/2019

Taken By: Bill Whalen

View to N across attic area and  
trusses / No visible damage from roof  
leakage noted.



## Montana Claims Service of Missoula

---

P.O. Box 4504  
Missoula, MT 59806  
Phone (406) 542-2580  
Fax (406) 543-2822  
Email MCSM@Montana.com

57 57-DSCN3780

Date Taken: 7/12/2019

Taken By: Bill Whalen

View to N across attic area and  
trusses / No visible damage from roof  
leakage noted.



## Montana Claims Service of Missoula

---

P.O. Box 4504  
Missoula, MT 59806  
Phone (406) 542-2580  
Fax (406) 543-2822  
Email MCSM@Montana.com

Insured: Department of FWP / Travelers Rest State Park  
Property: 6717 U.S. Hwy 12  
Lolo, MT 59847

Claim Rep.: Gordon Amsbaugh  
Company: Risk Management - State of Montana

Estimator: Bill Whalen  
Company: Montana Claims Service of Missoula

**Claim Number:** P28611-FW

**Policy Number:** N/A

**Type of Loss:** Weight of Ice & Snow

Date Contacted: 7/2/2019

Date of Loss: 1/1/2019

Date Inspected: 7/12/2019

Date Received: 6/28/2019

Date Entered: 7/15/2019 10:24 PM

Price List: MTMI8X\_JUL19  
Restoration/Service/Remodel  
Estimate: 100019-FWP\_INT\_PICS

## INTERIOR PHOTO SHEETS



## Montana Claims Service of Missoula

---

P.O. Box 4504  
Missoula, MT 59806  
Phone (406) 542-2580  
Fax (406) 543-2822  
Email MCSM@Montana.com

- 1 1-DSCN3957  
Date Taken: 7/12/2019  
Taken By: Bill Whalen  
Front entry at gift shop.



- 2 2-DSCN3956  
Date Taken: 7/12/2019  
Taken By: Bill Whalen  
View to S across gift shop - No water damage reported/noted.



## Montana Claims Service of Missoula

---

P.O. Box 4504  
Missoula, MT 59806  
Phone (406) 542-2580  
Fax (406) 543-2822  
Email MCSM@Montana.com

3 3-DSCN3962

Date Taken: 7/12/2019

Taken By: Bill Whalen

View to S across gift shop - No water damage reported/noted.



4 4-DSCN3958

Date Taken: 7/12/2019

Taken By: Bill Whalen

View to S across gift shop - No water damage reported/noted.



## Montana Claims Service of Missoula

---

P.O. Box 4504  
Missoula, MT 59806  
Phone (406) 542-2580  
Fax (406) 543-2822  
Email MCSM@Montana.com

5 5-DSCN3959

Date Taken: 7/12/2019

Taken By: Bill Whalen

View to N across gift shop - No water damage reported/noted.



6 6-DSCN3961

Date Taken: 7/12/2019

Taken By: Bill Whalen

View to N across gift shop - No water damage reported/noted.





## Montana Claims Service of Missoula

---

P.O. Box 4504  
Missoula, MT 59806  
Phone (406) 542-2580  
Fax (406) 543-2822  
Email MCSM@Montana.com

7 7-DSCN3855

Date Taken: 7/12/2019

Taken By: Bill Whalen

View to W from Gift Shop looking  
across main Museum Room - No  
water damage reported/noted in these  
areas.



8 8-DSCN3856

Date Taken: 7/12/2019

Taken By: Bill Whalen

View to W along S wall of main  
Museum Room - No water damage  
reported/noted in these areas.



## Montana Claims Service of Missoula

---

P.O. Box 4504  
Missoula, MT 59806  
Phone (406) 542-2580  
Fax (406) 543-2822  
Email MCSM@Montana.com

9 9-DSCN3857

Date Taken: 7/12/2019

Taken By: Bill Whalen

View to W along N wall of main  
Museum Room - Water damage  
reported/noted in the areas marked.



10 10-DSCN3860

Date Taken: 7/12/2019

Taken By: Bill Whalen

View to E along S wall of main  
Museum Room - No water damage  
reported/noted in these areas.



## Montana Claims Service of Missoula

---

P.O. Box 4504  
Missoula, MT 59806  
Phone (406) 542-2580  
Fax (406) 543-2822  
Email MCSM@Montana.com

11 11-DSCN3859

Date Taken: 7/12/2019

Taken By: Bill Whalen

View to E along N wall of main  
Museum Room - Water damage  
reported/noted in the areas marked.




12 12-DSCN3876

Date Taken: 7/12/2019

Taken By: Bill Whalen

View to E along N wall of main  
Museum Room adjacent to offices -  
Water damage reported/noted in the  
areas marked.





## Montana Claims Service of Missoula

---

P.O. Box 4504  
Missoula, MT 59806  
Phone (406) 542-2580  
Fax (406) 543-2822  
Email MCSM@Montana.com

13 13-DSCN3911

Date Taken: 7/12/2019

Taken By: Bill Whalen

View to E along N wall of main  
Museum Room adjacent to offices -  
Water damage reported/noted in the  
areas marked.



14 14-DSCN3877

Date Taken: 7/12/2019

Taken By: Bill Whalen

View to E along N wall of main  
Museum Room adjacent to offices -  
Water damage reported/noted in the  
areas marked.



## Montana Claims Service of Missoula

---

P.O. Box 4504  
Missoula, MT 59806  
Phone (406) 542-2580  
Fax (406) 543-2822  
Email MCSM@Montana.com

15 15-DSCN3879

Date Taken: 7/12/2019

Taken By: Bill Whalen

View to W along N wall of main  
Museum Room adjacent to offices -  
Water damage reported/noted in the  
areas marked.



16 16-DSCN3913

Date Taken: 7/12/2019

Taken By: Bill Whalen

View to W across ceiling at N wall of  
main Museum Room, adjacent to  
offices - Water damage  
reported/noted in the areas marked.



## Montana Claims Service of Missoula

---

P.O. Box 4504  
Missoula, MT 59806  
Phone (406) 542-2580  
Fax (406) 543-2822  
Email MCSM@Montana.com

17 17-DSCN3880

Date Taken: 7/12/2019

Taken By: Bill Whalen

View of Office 1 - Damage noted at  
tape joint as marked.




18 18-DSCN3881

Date Taken: 7/12/2019

Taken By: Bill Whalen

View of Office 1 - Damage noted at  
tape joint as marked.





## Montana Claims Service of Missoula

---

P.O. Box 4504  
Missoula, MT 59806  
Phone (406) 542-2580  
Fax (406) 543-2822  
Email MCSM@Montana.com

19 19-DSCN3882

Date Taken: 7/12/2019

Taken By: Bill Whalen

View to W along back wall of Office  
1 looking across open area into  
Offices 2 & 3 - No damage reported  
or noted.



20 20-DSCN3885

Date Taken: 7/12/2019

Taken By: Bill Whalen

View to W along front wall of Office  
1 looking across open area into  
Offices 2 - 8 / Damage reported/noted  
in areas marked.



## Montana Claims Service of Missoula

---

P.O. Box 4504  
Missoula, MT 59806  
Phone (406) 542-2580  
Fax (406) 543-2822  
Email MCSM@Montana.com

21 21-DSCN3887

Date Taken: 7/12/2019

Taken By: Bill Whalen

View into Office 2 - No damage  
reported/noted.



22 22-DSCN3888

Date Taken: 7/12/2019

Taken By: Bill Whalen

View into Office 2 - No damage  
reported/noted.



## Montana Claims Service of Missoula

---

P.O. Box 4504  
Missoula, MT 59806  
Phone (406) 542-2580  
Fax (406) 543-2822  
Email MCSM@Montana.com

23 23-DSCN3889

Date Taken: 7/12/2019

Taken By: Bill Whalen

View into Office 3 - No damage  
reported/noted.




24 24-DSCN3892

Date Taken: 7/12/2019

Taken By: Bill Whalen

View into Office 3 - No damage  
reported/noted.





## Montana Claims Service of Missoula

---

P.O. Box 4504  
Missoula, MT 59806  
Phone (406) 542-2580  
Fax (406) 543-2822  
Email MCSM@Montana.com

25 25-DSCN3893

Date Taken: 7/12/2019

Taken By: Bill Whalen

View into Office 3 - No damage reported/noted.



26 26-DSCN3894

Date Taken: 7/12/2019

Taken By: Bill Whalen

View along front wall of Offices 3,2  
& 1 - No damage reported/noted.



## Montana Claims Service of Missoula

---

P.O. Box 4504  
Missoula, MT 59806  
Phone (406) 542-2580  
Fax (406) 543-2822  
Email MCSM@Montana.com

27 27-DSCN3896

Date Taken: 7/12/2019

Taken By: Bill Whalen

View along front wall of Offices 4,-7  
- Damage reported/noted as marked.



28 28-DSCN3899

Date Taken: 7/12/2019

Taken By: Bill Whalen

View into Office 6/7 - Damage  
reported/noted along front wall but  
not rear wall shown.



## Montana Claims Service of Missoula

---

P.O. Box 4504  
Missoula, MT 59806  
Phone (406) 542-2580  
Fax (406) 543-2822  
Email MCSM@Montana.com

29 29-DSCN3898

Date Taken: 7/12/2019

Taken By: Bill Whalen

View to E across Office 6/7 - Damage reported/noted along front wall but not rear wall shown.



30 30-DSCN3900

Date Taken: 7/12/2019

Taken By: Bill Whalen

View along front wall of Offices 6-7 - Damage reported/noted as marked.





## Montana Claims Service of Missoula

---

P.O. Box 4504  
Missoula, MT 59806  
Phone (406) 542-2580  
Fax (406) 543-2822  
Email MCSM@Montana.com

31 31-DSCN3901

Date Taken: 7/12/2019

Taken By: Bill Whalen

View along front wall of Offices 6-7 -  
Damage reported/noted as marked.



32 32-DSCN3902

Date Taken: 7/12/2019

Taken By: Bill Whalen

View along front wall of Offices 6-7 -  
Damage reported/noted as marked.



## Montana Claims Service of Missoula

---

P.O. Box 4504  
Missoula, MT 59806  
Phone (406) 542-2580  
Fax (406) 543-2822  
Email MCSM@Montana.com

33 33-DSCN3903

Date Taken: 7/12/2019

Taken By: Bill Whalen

View into Office 38- No damage  
reported/noted.



34 34-DSCN3906

Date Taken: 7/12/2019

Taken By: Bill Whalen

View to E across Office 8 - No  
damage reported/noted.



## Montana Claims Service of Missoula

---

P.O. Box 4504  
Missoula, MT 59806  
Phone (406) 542-2580  
Fax (406) 543-2822  
Email MCSM@Montana.com

35 35-DSCN3905

Date Taken: 7/12/2019

Taken By: Bill Whalen

View to W across Office 8 - No  
damage reported/noted.



36 36-DSCN3907

Date Taken: 7/12/2019

Taken By: Bill Whalen

View to W across Mechanical Room,  
connected to Office 8 - No damage  
reported/noted.





## Montana Claims Service of Missoula

---

P.O. Box 4504  
Missoula, MT 59806  
Phone (406) 542-2580  
Fax (406) 543-2822  
Email MCSM@Montana.com

37 37-DSCN3910

Date Taken: 7/12/2019

Taken By: Bill Whalen

View to W across Mechanical Room,  
connected to Office 8 - No damage  
reported/noted.



38 38-DSCN3947

Date Taken: 7/12/2019

Taken By: Bill Whalen

View to W along Hallway from  
Museum Room toward bathrooms -  
No damages reported/noted.



## Montana Claims Service of Missoula

---

P.O. Box 4504  
Missoula, MT 59806  
Phone (406) 542-2580  
Fax (406) 543-2822  
Email MCSM@Montana.com

39 39-DSCN3948

Date Taken: 7/12/2019

Taken By: Bill Whalen

View from Hall into Men's Bathroom  
- No damage reported/noted.



40 40-DSCN3949

Date Taken: 7/12/2019

Taken By: Bill Whalen

View from Hall into Men's Bathroom  
- Ceiling detail with no damage  
reported/noted.



## Montana Claims Service of Missoula

---

P.O. Box 4504  
Missoula, MT 59806  
Phone (406) 542-2580  
Fax (406) 543-2822  
Email MCSM@Montana.com

41 41-DSCN3950

Date Taken: 7/12/2019

Taken By: Bill Whalen

View from Hall into Men's Bathroom  
- Ceiling detail with no damage  
reported/noted.



42 42-DSCN3951

Date Taken: 7/12/2019

Taken By: Bill Whalen

View from Hall into Women's  
Bathroom - No damage  
reported/noted.





## Montana Claims Service of Missoula

---

P.O. Box 4504  
Missoula, MT 59806  
Phone (406) 542-2580  
Fax (406) 543-2822  
Email MCSM@Montana.com

43 43-DSCN3952

Date Taken: 7/12/2019

Taken By: Bill Whalen

View across Women's Bathroom - No  
damage reported/noted.



44 44-DSCN3954

Date Taken: 7/12/2019

Taken By: Bill Whalen

View across Women's Bathroom -  
Ceiling detail with no damage  
reported/noted.



## Montana Claims Service of Missoula

---

P.O. Box 4504  
Missoula, MT 59806  
Phone (406) 542-2580  
Fax (406) 543-2822  
Email MCSM@Montana.com

45 45-DSCN3955

Date Taken: 7/12/2019

Taken By: Bill Whalen

View across Women's Bathroom -  
Ceiling detail with no damage  
reported/noted.



46 46-DSCN3862

Date Taken: 7/12/2019

Taken By: Bill Whalen

View from Museum door looking  
across Multi Purpose Room with no  
damage reported/noted.



## Montana Claims Service of Missoula

---

P.O. Box 4504  
Missoula, MT 59806  
Phone (406) 542-2580  
Fax (406) 543-2822  
Email MCSM@Montana.com

47 47-DSCN3863

Date Taken: 7/12/2019

Taken By: Bill Whalen

View to SW from Museum door  
looking across Multi Purpose Room  
with no damage reported/noted.



48 48-DSCN3864

Date Taken: 7/12/2019

Taken By: Bill Whalen

View to NW from Museum door  
looking across Multi Purpose Room  
with no damage reported/noted.





## Montana Claims Service of Missoula

---

P.O. Box 4504  
Missoula, MT 59806  
Phone (406) 542-2580  
Fax (406) 543-2822  
Email MCSM@Montana.com

49 49-DSCN3866

Date Taken: 7/12/2019

Taken By: Bill Whalen

View to NE looking across Multi Purpose Room with no damage reported/noted.



50 50-DSCN3868

Date Taken: 7/12/2019

Taken By: Bill Whalen

View across Multi Purpose Room - Ceiling detail with no damage reported/noted.



## Montana Claims Service of Missoula

---

P.O. Box 4504  
Missoula, MT 59806  
Phone (406) 542-2580  
Fax (406) 543-2822  
Email MCSM@Montana.com

51 51-DSCN3867

Date Taken: 7/12/2019

Taken By: Bill Whalen

View to SE looking across Multi Purpose Room with no damage reported/noted.



52 52-DSCN3869

Date Taken: 7/12/2019

Taken By: Bill Whalen

View across Multi Purpose Room -  
Ceiling detail with no damage  
reported/noted.



## Montana Claims Service of Missoula

---


P.O. Box 4504  
Missoula, MT 59806  
Phone (406) 542-2580  
Fax (406) 543-2822  
Email MCSM@Montana.com

53 53-DSCN3873

Date Taken: 7/12/2019

Taken By: Bill Whalen

View across Multi Purpose Room -  
Ceiling detail with no damage  
reported/noted.



54 54-DSCN3914

Date Taken: 7/12/2019

Taken By: Bill Whalen

View from Museum Room to S into  
Old West Display room.





## Montana Claims Service of Missoula

---

P.O. Box 4504  
Missoula, MT 59806  
Phone (406) 542-2580  
Fax (406) 543-2822  
Email MCSM@Montana.com

55 55-DSCN3915

Date Taken: 7/12/2019

Taken By: Bill Whalen

View to W across Old West Display  
room with no damage reported/noted.



56 56-DSCN3916

Date Taken: 7/12/2019

Taken By: Bill Whalen

View to the east across Old West Display  
room with no damage reported/noted.



## Montana Claims Service of Missoula

---

P.O. Box 4504  
Missoula, MT 59806  
Phone (406) 542-2580  
Fax (406) 543-2822  
Email MCSM@Montana.com

57 57-DSCN3920

Date Taken: 7/12/2019

Taken By: Bill Whalen

View to W across Storage Room 1  
with no damage reported/noted in this  
area.



58 58-DSCN3917

Date Taken: 7/12/2019

Taken By: Bill Whalen

View to the east across Storage Area 1 with  
damage reported/noted at  
ceiling/upper wall as marked.



## Montana Claims Service of Missoula

P.O. Box 4504  
Missoula, MT 59806  
Phone (406) 542-2580  
Fax (406) 543-2822  
Email MCSM@Montana.com

59 59-DSCN3918

Date Taken: 7/12/2019

Taken By: Bill Whalen

Museum displays and articles located  
in Storage Area 1 with no damage  
noted/noted.



60 60-DSCN3919

Date Taken: 7/12/2019

Taken By: Bill Whalen

View at E end of Storage Area 1 with  
damage reported/noted at  
ceiling/upper wall as marked.





## Montana Claims Service of Missoula

---

P.O. Box 4504  
Missoula, MT 59806  
Phone (406) 542-2580  
Fax (406) 543-2822  
Email MCSM@Montana.com

61 61-DSCN3929

Date Taken: 7/12/2019

Taken By: Bill Whalen

View at E end of Storage Area 1 with  
damage reported/noted at  
ceiling/upper wall as marked.



62 62-DSCN3922

Date Taken: 7/12/2019

Taken By: Bill Whalen

View to E across Storage Area 2  
with water seepage through ceiling  
reported in area marked.

Museum displays and articles located  
in Storage Area 1 with no damage  
noted/noted.



## Montana Claims Service of Missoula

---

P.O. Box 4504  
Missoula, MT 59806  
Phone (406) 542-2580  
Fax (406) 543-2822  
Email MCSM@Montana.com

63 63-DSCN3923

Date Taken: 7/12/2019

Taken By: Bill Whalen

View to W across Storage Area 2 with  
water seepage through ceiling  
reported in area marked.

Museum displays and articles located  
in Storage Area 1 with no damage  
noted/noted.




64 64-DSCN3924

Date Taken: 7/12/2019

Taken By: Bill Whalen

View to W across Storage Area 2 with  
water seepage through ceiling  
reported in area marked.

Museum displays and articles located  
in Storage Area 1 with no damage  
noted/noted.



## Montana Claims Service of Missoula

---

P.O. Box 4504  
Missoula, MT 59806  
Phone (406) 542-2580  
Fax (406) 543-2822  
Email MCSM@Montana.com

65 65-DSCN3925

Date Taken: 7/12/2019

Taken By: Bill Whalen

View to W across Storage Area 2 with  
water seepage through ceiling  
reported in area marked.



66 66-DSCN3926

Date Taken: 7/12/2019

Taken By: Bill Whalen

View to W across Storage Area 2 with  
water seepage through ceiling  
reported in area marked.





## Montana Claims Service of Missoula

---

P.O. Box 4504  
Missoula, MT 59806  
Phone (406) 542-2580  
Fax (406) 543-2822  
Email MCSM@Montana.com

67 67-DSCN3930

Date Taken: 7/12/2019

Taken By: Bill Whalen

View to E across Administrative  
Office 2 with no water damage  
reported/noted.



68 68-DSCN3931

Date Taken: 7/12/2019

Taken By: Bill Whalen

View to W across Administrative  
Office 2 with no water damage  
reported/noted.



## Montana Claims Service of Missoula

P.O. Box 4504  
Missoula, MT 59806  
Phone (406) 542-2580  
Fax (406) 543-2822  
Email MCSM@Montana.com

69 69-DSCN3934

Date Taken: 7/12/2019

Taken By: Bill Whalen

View to W across Administrative  
Office 1 with no water infiltration  
through ceiling in area marked.



70 70-DSCN3935

Date Taken: 7/12/2019

Taken By: Bill Whalen

View to W across Administrative  
Office 1 with no water infiltration  
through ceiling in area marked.



## Montana Claims Service of Missoula

---

P.O. Box 4504  
Missoula, MT 59806  
Phone (406) 542-2580  
Fax (406) 543-2822  
Email MCSM@Montana.com

71 71-DSCN3936

Date Taken: 7/12/2019

Taken By: Bill Whalen

View to E across Administrative  
Office 2 with no water damage  
reported/noted in this area.



72 72-DSCN3946

Date Taken: 7/12/2019

Taken By: Bill Whalen

View to E across Chapel with water  
infiltration through ceiling in area  
marked.





## Montana Claims Service of Missoula

---

P.O. Box 4504  
Missoula, MT 59806  
Phone (406) 542-2580  
Fax (406) 543-2822  
Email MCSM@Montana.com

73 73-DSCN3937

Date Taken: 7/12/2019

Taken By: Bill Whalen

View to W across Chapel with water infiltration through ceiling in area marked.




74 74-DSCN3941

Date Taken: 7/12/2019

Taken By: Bill Whalen

View to W across Chapel with water infiltration through ceiling in area marked.



## Montana Claims Service of Missoula

---

P.O. Box 4504  
Missoula, MT 59806  
Phone (406) 542-2580  
Fax (406) 543-2822  
Email MCSM@Montana.com

75 75-DSCN3940

Date Taken: 7/12/2019

Taken By: Bill Whalen

View to E across Chapel with water infiltration through ceiling in area marked.



76 76-DSCN3944

Date Taken: 7/12/2019

Taken By: Bill Whalen

View to W across Chapel with water infiltration through ceiling in area marked.



## Montana Claims Service of Missoula

---

P.O. Box 4504  
Missoula, MT 59806  
Phone (406) 542-2580  
Fax (406) 543-2822  
Email MCSM@Montana.com

77 77-DSCN3942

Date Taken: 7/12/2019

Taken By: Bill Whalen

View at NW corner of Chapel with no  
water infiltration reported or noted in  
this area.

